
Vestone, 10 October 2026

SUBJECT: update for floating valves VS0800218 e VS0800219

Herby we inform you that the “dual-adjustment” type float valves—supplied both in external cisterns and as spare parts—have been modified: the adjustment screw has been eliminated and replaced by a setting system using notches integrated in the vertical part and on the floating box

	
Previous version	Current version

The water level is adjusted by moving the floating box up or down to the positions indicated by the marks (see the instruction below).



CASSETTA - *CISTERN*	A	B TACCHE - *MARKS*
CORALLO3 - MIDA - MUREX	65±2	2
ATLANTA - ISLAND - SOLEA	80±2	3
CUBIK	83,5±2	4

CASSETTA - *CISTERN*	A TACCHE - *MARKS*	B TACCHE - *MARKS*
CORALLO3 - MIDA MUREX	5	2
ATLANTA - ISLAND SOLEA	11	3
CUBIK	11	4

At disposal for further clarifications

VALSIR SPA

eng. Luca Bettini

VALSIR S.p.A. - Società a Socio Unico
Località Merlaro, 2 - 25078 Vestone (BS) - Italy
Tel. +39 0365 877.011 - Fax +39 0365 81268 - E-mail: valsir@valsir.it - **www.valsir.it**
Cap. Soc. €90.000.000 int. vers. - cod. fisc. e Reg. Imp. Brescia 02878210174
P.IVA 00700170988 - R.E.A. c.c.i.a.a. Bs 301171 - Mecc. Bs 001856
Soggetta all'attività di direzione e coordinamento da parte di SILMAR GROUP S.p.A.
C.F. 02075160172

s_280.03_Vdf-Rev1